



Product Catalogue

2023

www.winmarktruck.com.tr

TRUCK SPARE PARTS



info@winmarktruck.com.tr



+90 542 332 6640



www.winmarktruck.com.tr

► **FREN SİSTEMİ HAVA KURUTUCU TAMİR TAKIMLARI / BRAKE SYSTEM AIR DRYER REPAIR KITS**



4-16

► **FREN PEDAL VALFİ TAMİR TAKIMLARI / FOOT BRAKE VALVE REPAIR KITS**



17-22

► **DEBRİAJ ALT MERKEZ & ELEKTRİKLİ DEBRİAJ MERKEZİ TAMİR TAKIMLARI / CLUTCH SERVO & CLUTCH ACTUATOR REPAIR KITS**



23-31

► **ABS & EBS VALFİ TAMİR TAKIMLARI / ABS & EBS VALVE REPAIR KITS**



32-34

► **ECAS SELENOİD VALF TAMİR TAKIMLARI / ECAS SOLENOID VALVE REPAIR KITS**



35-39

► **ROLE VENTİLİ TAMİR TAKIMLARI / RELAY VALVE REPAIR KITS**



40-42

► **ŞANZİMAN VALFİ TAMİR TAKIMLARI / GEARBOX VALVE REPAIR KITS**



43-46

► **DORSE KONTROL VALFİ TAMİR TAKIMLARI / TRAILER CONTROL VALVE REPAIR KITS**



47-48

► **EL FREN VALFİ TAMİR TAKIMI / HANDBRAKE VALVE REPAIR KIT**




49-53

► **TAZYİK SİBOPLARI / PRESSURE VALVES**



54-60



Air Dryer Distributor Repair Kit

Fully assembled product



201.001.001.2

Oem Ref	Vehicle/Model	Engine
432 410 000 2	Bmc	432
	Man	410
	Ford	
	Daf	
	Scania	
	Mercedes	

Repair kit



Fully assembled product



201.001.002.2

Oem Ref	Vehicle/Model	Engine
932 400 003 0	Bmc	
	Man	
	Ford	
	Daf	
	Scania	
	Mercedes	

Repair kit



Fully assembled product



201.001.003.2

Oem Ref	Vehicle/Model	Engine
	Mercedes	432 410
	Man	432 11
	Daf	432 415
	Scania	
	Ford	
	Bmc	

Repair kit



Fully assembled product



201.001.004.2

Oem Ref	Vehicle/Model	Engine
432 410 001 2		432 410
81 52102 6032		432 11
1932671		432 415

Repair kit



Fully assembled product



201.001.005.2

Oem Ref	Vehicle/Model	Engine
932 400 003 0	Mercedes	432 410
932 400 001 2	Man	
	Daf	
	Scania	
	Ford	
	Bmc	

Repair kit



Fully assembled product



201.001.006.2

Oem Ref	Vehicle/Model	Engine
	Mercedes	432 410
	Man	
	Daf	
	Scania	
	Ford	
	Bmc	

Repair kit



Fully assembled product



201.001.007.2

Oem Ref	Vehicle/Model	Engine
432 410 002 2	Mercedes	432 410
	Man	432 11
	Daf	432 415
	Scania	
	Ford	
	Bmc	

Repair kit



Fully assembled product



201.001.008.2

Oem Ref	Vehicle/Model	Engine
432 410 002 2	Mercedes	432 410
	Man	432 11
	Daf	432 415
	Scania	
	Ford	
	Bmc	

Repair kit



Fully assembled product



201.001.009.2

Oem Ref	Vehicle/Model	Engine
432 415 000 0	Ford	Cargo
432 415 002 0	Renault	Erf
432 415 003 0	Kamaz	IV
432 415 000 2		

Repair kit



Fully assembled product



201.001.010.2

Oem Ref	Vehicle/Model	Engine
432 415 000 0	Ford	Cargo
432 415 002 0	Renault	Erf
432 415 003 0	Kamaz	IV
432 415 000 2		

Repair kit



Air Dryer Distributor Repair Kit

Fully assembled product



201.001.011.2

Oem Ref	Vehicle/Model	Engine
190121	Man Daf Volvo Iveco	LA 6200 LA 6204 LA 6700

Repair kit



Fully assembled product



201.001.012.2

Oem Ref	Vehicle/Model	Engine
190121	Man Daf Volvo Iveco	LA 6200 LA 6204 LA 6700

Repair kit



Fully assembled product



201.001.013.2

Oem Ref	Vehicle/Model	Engine
	Man Mfg L2000 M2000	LA6200 LA6204 LA6277

Repair kit



Fully assembled product



201.001.014.2

Oem Ref	Vehicle/Model	Engine
	Man Mfg L2000 M2000	LA6200 LA6204 LA6277

Repair kit



Fully assembled product



201.001.015.2

Oem Ref	Vehicle/Model	Engine
190121	Man Volvo	LA6700 LA6709 LA6735

Repair kit



Fully assembled product



201.001.016.2

Oem Ref	Vehicle/Model	Engine
190121	Man Volvo	LA6700 LA6709 LA6735

Repair kit



Fully assembled product



201.001.017.2

Oem Ref	Vehicle/Model	Engine
K003442	Mercedes Man Volvo Renault Iveco Bmc	LA80.. LA81..

Repair kit




Fully assembled product



201.001.018.2

Oem Ref	Vehicle/Model	Engine
	Mercedes Actros Atego Axor Iveco	LA90..

Repair kit



Fully assembled product



201.001.019.2

Oem Ref	Vehicle/Model	Engine
	Mercedes Actros Atego Axor Iveco	LA90..

Repair kit




Fully assembled product



201.001.020.2

Oem Ref	Vehicle/Model	Engine
1137677008	Daf Iveco	LA8116 LA8117 LA8157

Repair kit



Fully assembled product



201.001.021.2

Oem Ref	Vehicle/Model	Engine
1137677008	Daf Iveco	LA8116 LA8117 LA8157

Repair kit



Fully assembled product



201.001.022.2

Oem Ref	Vehicle/Model	Engine
1137677008	Daf Iveco	LA8116 LA8117 LA8157

Repair kit



Fully assembled product



201.003.001.2

Oem Ref	Vehicle/Model	Engine
	Renault IV Mercedes 2225 Kerax Magnum	EL1100

Repair kit



Fully assembled product



201.003.002.2

Oem Ref	Vehicle/Model	Engine
	Renault IV Mercedes 2225 Kerax Magnum	EL1100

Repair kit




Fully assembled product



201.003.003.2

Oem Ref	Vehicle/Model	Engine
	Renault IV Mercedes 2225 Kerax Magnum	EL1100

Repair kit



Fully assembled product



201.001.023.2

Oem Ref	Vehicle/Model	Engine
1 487 0 10 102	Mercedes	
0484 460 024	Man	
	Daf	
	Renault	
	Iveco	

Repair kit



Fully assembled product



201.003.004.2

Oem Ref	Vehicle/Model	Engine
1 487 0 10 102	Scania	
932 510 000 0		
932 510 001 0		
932 510 100 0		

Repair kit



Fully assembled product



201.001.024.2

Oem Ref	Vehicle/Model	Engine
432 425 001 0	VOLVO FH/FM	
432 425 004 0		
432 425 200 0		

Repair kit



Fully assembled product



201.001.025.2

Oem Ref	Vehicle/Model	Engine
432 425 001 0	VOLVO FH/FM	
432 425 004 0		
432 425 200 0		

Repair kit



Fully assembled product



201.001.026.2

Oem Ref	Vehicle/Model	Engine
432 425 922 2	VOLVO FH/FM	
432 425 001 0		
432 425 004 0		
432 425 200 0		

Repair kit




Fully assembled product



201.003.004.2

Oem Ref	Vehicle/Model	Engine
	Mercedes	ZB 4800
	Man	ZB 4801
		ZB 4809

Repair kit




Fully assembled product



201.003.005.2

Oem Ref	Vehicle/Model	Engine
	Daf	ZB 4586
	Iveco	ZB 4587
		ZB 4588

Repair kit




Fully assembled product



201.003.006.2

Oem Ref	Vehicle/Model	Engine
	Mercedes	ZB 4504
	Daf	ZB 4505
	Iveco	ZB 4534

Repair kit



Fully assembled product



201.003.007.2

Oem Ref	Vehicle/Model	Engine
932 500 003 0	Mercedes	Actros
932 500 004 0		Axor
932 500 021 0		Atego
		Evobus

Repair kit



Fully assembled product



201.003.008.2

Oem Ref	Vehicle/Model	Engine
932 500 003 0	Mercedes	Actros
932 500 004 0		Axor
932 500 021 0		Atego
		Evobus

Repair kit



Fully assembled product



201.003.009.2

Oem Ref	Vehicle/Model	Engine
	Ford	Cargo
		ZB 4400
		ZB 4402
		ZB 4427

Repair kit



Fully assembled product



201.003.010.2

Oem Ref	Vehicle/Model	Engine
	Ford	Cargo
		ZB 4400
		ZB 4402
		ZB 4427

Repair kit



Fully assembled product



201.003.011.2

Oem Ref	Vehicle/Model	Engine
	Mercedes	EL 2201

Repair kit




Fully assembled product



201.003.012.2

Oem Ref	Vehicle/Model	Engine
	Iveco	ZB 4601
	Tector	ZB 4602
	Euro cargo	ZB 4611

Repair kit



Fully assembled product



201.004.001.2

Oem Ref	Vehicle/Model	Engine
975 303 *** 2432	Mercedes	
975 303 494 0	Man	
975 303 473 0	Daf	
975 303 663 0	Scania	
	Renault	
	Iveco	
	Bmc	

Repair kit



Fully assembled product



201.004.002.2

Oem Ref	Vehicle/Model	Engine
975 303 *** 2432	Mercedes	
975 303 494 0	Man	
975 303 473 0	Daf	
975 303 663 0	Scania	
	Renault	
	Iveco	
	Bmc	

Repair kit



Fully assembled product



201.004.004.2

Oem Ref	Vehicle/Model	Engine
975 300 000 2	Mercedes	975 300 SERIES
	Man	
	Daf	
	Renault	
	Iveco	

Repair kit



Fully assembled product



201.004.005.2

Oem Ref	Vehicle/Model	Engine
973 500 028 0	Mercedes	
	Daf	
	Iveco	
	Ford	
	Bmc	
	Dodge	
	Inter	

Repair kit



Fully assembled product



201.004.007.2

Oem Ref	Vehicle/Model	Engine
1 487 010 314	Mercedes	
0 481 039 201	Daf	
0 481 039 202	Scania	
0481 039 241	Renault	
	Iveco	

Repair kit




Fully assembled product



201.002.001.2

Oem Ref	Vehicle/Model	Engine
634 705 002 0	Mercedes	axor
934 705 003 0		atego
934 705 005 0		actros

Repair kit




Fully assembled product



201.002.003.2

Oem Ref	Vehicle/Model	Engine
634 705 002 0	Mercedes	axor
934 705 003 0		atego
934 705 005 0		actros

Repair kit




Fully assembled product



201.002.004.2

Oem Ref	Vehicle/Model	Engine
1137680 / 0051 AE4510	Mercedes Actros Atego Axor Evobus	

Repair kit



Fully assembled product



201.002.005.2

Oem Ref	Vehicle/Model	Engine
	Mercedes	AE480 AE4802

Repair kit




Fully assembled product



201.002.006.2

Oem Ref	Vehicle/Model	Engine
		FOR AE 4560 - AE 4563 AE 4561 - AE 4560 AE 4562

Repair kit




Fully assembled product



201.002.007.2

Oem Ref	Vehicle/Model	Engine
		FOR AE 46 SERIES

Repair kit



Fully assembled product



201.002.008.2

Oem Ref	Vehicle/Model	Engine
II15588008		FOR AE 4408 AE 4427 AE 4428

Repair kit



Fully assembled product



201.002.009.2

Oem Ref	Vehicle/Model	Engine
SEB22144		FOR AE 4440 AE 4196 AE 4449 AE 4451

Repair kit



Fully assembled product



201.002.010.2

Oem Ref	Vehicle/Model	Engine
I706150051		FOR AE 4158

Repair kit



Fully assembled product



201.002.011.2

Oem Ref	Vehicle/Model	Engine
		FOR 934 714 140 0 934 714 740 0

Repair kit



Fully assembled product



201.002.012.2

Oem Ref	Vehicle/Model	Engine
934 702 006 2		

Repair kit





Foot Brake Valve Repair Kit

www.winmarktruck.com.tr

Fully assembled product



202.001.001.2

Oem Ref	Vehicle/Model	Engine
461 315 008 2	Mercedes	
461 315 018 0	Man	
461 315 046 0	Daf	
461 315 474 0	Volvo	
	Ford	
	Bmc	

Repair kit



Fully assembled product



202.001.002.2

Oem Ref	Vehicle/Model	Engine
461 315 901 2	Mercedes	
461 315 018 0	Man	
461 315 046 0	Daf	
461 315 474 0	Volvo	
	Ford	
	Bmc	

Repair kit



Fully assembled product



202.001.003.2

Oem Ref	Vehicle/Model	Engine
461 315 927 2	Mercedes	Axor
461 315 264 0	Ford	Cargo
461 315 267 0		

Repair kit



Axor Yeni Model – İnce Sibop


Fully assembled product



202.001.004.2

Oem Ref	Vehicle/Model	Engine
461 315 005 2	Mercedes	Axor
461 315 264 0	Ford	Cargo
461 315 267 0		

Repair kit



Ford Cargo

Fully assembled product



202.001.005.2

Oem Ref	Vehicle/Model	Engine
461 315 914 2	Mercedes	
461 315 264 0		

Repair kit



Fully assembled product



202.001.006.2

Oem Ref	Vehicle/Model	Engine
461 319 912 2 461 319 273 0	Mercedes	Actros

Repair kit



Mercedes Actros

Fully assembled product



202.001.007.2

Oem Ref	Vehicle/Model	Engine
K039530 K037544 0486 200 004	Man Scania Volvo Renault Iveco	Tga

Repair kit



Fully assembled product



202.001.008.2

Oem Ref	Vehicle/Model	Engine
480 001 000 0 480 001 004 0 480 001 500 0	Mercedes Daf	Actros Evobus

Repair kit




Fully assembled product



202.001.009.2

Oem Ref	Vehicle/Model	Engine
950 320 020	Man	M/L/F 2000 320 060 SERIES 320 062 SERIES 320 063 SERIES

Repair kit



Fully assembled product



202.001.010.2

Oem Ref	Vehicle/Model	Engine
950 320 020	Man	M/L/F 2000 320 060 SERIES 320 062 SERIES 320 063 SERIES

Repair kit



Fully assembled product



202.001.011.2

Oem Ref	Vehicle/Model	Engine
1 487 010 219 0 481 064 701	Scania	3-4-5 SERIES

Repair kit



Fully assembled product



202.001.012.2

Oem Ref	Vehicle/Model	Engine
076620002000	Iveco Euro Cargo	DX75A DX75B DX95BY

Repair kit



Fully assembled product



202.001.013.2

Oem Ref	Vehicle/Model	Engine
1 487 010 338 0481 064 105	Mercedes Volvo	

Repair kit



Fully assembled product



202.001.014.2

Oem Ref	Vehicle/Model	Engine
1114119008	Daf	MB4694 MB4643

Repair kit



Fully assembled product



202.001.015.2

Oem Ref	Vehicle/Model	Engine
	Man	F/M90, F/L/M2000 MB4673 MB4674 MB4683

Repair kit



Fully assembled product



202.001.016.2

Oem Ref	Vehicle/Model	Engine
	Ford	Cargo GA/29308 APGA/6715 APGA/6620

Repair kit




Fully assembled product



202.001.017.2

Oem Ref	Vehicle/Model	Engine
	Scania	3-4-5 SERIES DX70C

Repair kit



Fully assembled product



202.001.018.2

Oem Ref	Vehicle/Model	Engine
	Iveco	DX52B DX52BY

Repair kit



Fully assembled product



202.001.019.2

Oem Ref	Vehicle/Model	Engine
461 315 924 2 461 318 180 0	Scania	

Repair kit



Fully assembled product



202.001.020.2

Oem Ref	Vehicle/Model	Engine
	Daf Iveco	DX60A Stralis Irisbus Eurotech

Repair kit



Fully assembled product



202.001.021.2

Oem Ref	Vehicle/Model	Engine
0 486 200 101 0 486 200 104 K001428	Renault	IV Premium Magnum Ebs5

Repair kit



Fully assembled product



202.001.022.2

Oem Ref	Vehicle/Model	Engine
461 494 502 0	Renault	Premium Kerax

Repair kit



Fully assembled product



202.001.023.2

Oem Ref	Vehicle/Model	Engine
480 001 300 0	Iveco	Stralis

Repair kit



Fully assembled product



202.001.024.2

Oem Ref	Vehicle/Model	Engine
K000926 K039530 0 486 200 007	Man	Tga Ebs2

Repair kit




Fully assembled product




202.001.025.2

Oem Ref	Vehicle/Model	Engine
480 002 002 0 480 002 004 0 480 003 000 0	Mercedes	

Repair kit





Clutch Center Repair Kit



www.winmarktruck.com.tr

Fully assembled product



203.001.001.2

Oem Ref	Vehicle/Model	Engine
970 051 949 2	Mercedes	
970 051 405 0	Man	
1519292	Daf	

Repair kit



Fully assembled product



203.001.002.2

Oem Ref	Vehicle/Model	Engine
970 051 961 2	Mercedes	
970 051 414 0	Man	
	Daf	

Repair kit



Fully assembled product



203.001.003.2

Oem Ref	Vehicle/Model	Engine
970 051 405 0	Mercedes	
	Man	
	Daf	

Repair kit



Fully assembled product



203.001.004.2

Oem Ref	Vehicle/Model	Engine
970 051 414 0	Mercedes	
	Man	
	Daf	

Repair kit



Fully assembled product



203.001.005.2

Oem Ref	Vehicle/Model	Engine
970 051 952 2	Man	
970 051 406 0	Daf	

Repair kit



Fully assembled product



203.001.006.2

Oem Ref	Vehicle/Model	Engine
970 051 977 2	Man	TGA
970 051 432 0	Daf	TGM

Repair kit




Fully assembled product



203.001.007.2

Oem Ref	Vehicle/Model	Engine
970 051 406 0	Man	
	Daf	

Repair kit



Fully assembled product



203.001.008.2

Oem Ref	Vehicle/Model	Engine
970 051 432 0	Man	TGA
	Daf	TGM

Repair kit



Fully assembled product



203.001.009.2

Oem Ref	Vehicle/Model	Engine
970 051 971 2	Mercedes	
970 051 412 0	Man	
	Daf	

Repair kit



Fully assembled product



203.001.010.2

Oem Ref	Vehicle/Model	Engine
970 051 412 0	Mercedes	
970 051 441 0	Man	
	Daf	

Repair kit



Clutch Center Repair Kit

Fully assembled product



203.001.011.2

Oem Ref	Vehicle/Model	Engine
970 051 412 0	Mercedes	
970 051 441 0	Man	
	Daf	

Repair kit



Fully assembled product



203.001.012.2

Oem Ref	Vehicle/Model	Engine
970 051 412 0	Mercedes	
	Man	
	Daf	

Repair kit




Fully assembled product



203.001.013.2

Oem Ref	Vehicle/Model	Engine
I84613	Man	
VG3200	Bus	
	M/L2000	

Repair kit




Fully assembled product



203.001.014.2

Oem Ref	Vehicle/Model	Engine
VG3200	Man	
	Bus	
	M/L2000	

Repair kit



Fully assembled product



203.001.015.2

Oem Ref	Vehicle/Model	Engine
K006731	Man	VG3208
		VG3209
		VG3224

Repair kit



Fully assembled product



203.001.016.2

Oem Ref	Vehicle/Model	Engine
I880940051	Man	VG3208 VG3209 VG3224

Repair kit



Fully assembled product



203.001.017.2

Oem Ref	Vehicle/Model	Engine
970 051 910 2 970 051 129 0	Mercedes Man Daf	

Repair kit



Fully assembled product



203.001.018.2

Oem Ref	Vehicle/Model	Engine
970 051 129 0	Mercedes Man Daf	

Repair kit



Fully assembled product



203.001.019.2

Oem Ref	Vehicle/Model	Engine
970 051 906 2 970 051 107 0 970 051 124 0 970 051 194 0	Mercedes Man Bmc	

Repair kit



Fully assembled product



203.001.020.2

Oem Ref	Vehicle/Model	Engine
970 051 906 2 970 051 107 0 970 051 124 0 970 051 194 0	Mercedes Man Bmc	

Repair kit



Clutch Center Repair Kit

Fully assembled product



203.001.021.2

Oem Ref	Vehicle/Model	Engine
	Ford Bmc Dodge	GA29317 APGA/1605/P Cargo

Repair kit



Fully assembled product



203.001.022.2

Oem Ref	Vehicle/Model	Engine
	Ford Bmc Dodge	GA29317 APGA/1605/P Cargo

Repair kit



Fully assembled product



203.001.023.2

Oem Ref	Vehicle/Model	Engine
970 051 916 2 970 051 146 0 970 051 147 0 970 051 158 0	Mercedes Man Daf	

Repair kit



Fully assembled product



203.001.024.2

Oem Ref	Vehicle/Model	Engine
321 024 001 321 027 001	Mercedes	Actros Axor

Repair kit




Fully assembled product



203.001.025.2

Oem Ref	Vehicle/Model	Engine
321 025 001 MINERAL OIL PENTOSIN	Mercedes	Actros Axor

Repair kit




Fully assembled product

203.001.026.2



Oem Ref	Vehicle/Model	Engine
321 025 001 MINERAL OIL PENTOSIN	Mercedes	Actros Axor

Repair kit



Fully assembled product

203.001.027.2



Oem Ref	Vehicle/Model	Engine
970 051 910 2 970 051 129 0	Mercedes Man Daf	EL1100

Repair kit



Fully assembled product

203.001.028.2



Oem Ref	Vehicle/Model	Engine
970 051 129 0	Mercedes Man Daf	EL1100

Repair kit



Fully assembled product

203.001.029.2



Oem Ref	Vehicle/Model	Engine
II14195008	Mercedes	VG3361

Repair kit



Fully assembled product

203.001.030.2



Oem Ref	Vehicle/Model	Engine
	Iveco Irisbus	VG3286

Repair kit



Clutch Center Repair Kit


Fully assembled product



203.001.031.2

Oem Ref	Vehicle/Model	Engine
626392AM	Volvo	FH 10/12/17

Repair kit




Fully assembled product



203.001.032.2

Oem Ref	Vehicle/Model	Engine
622095AM 626639AM	Volvo	FH 10/12/17

Repair kit




Fully assembled product



203.001.033.2

Oem Ref	Vehicle/Model	Engine
628476AM 628493AM 628494AM 629276AM	Volvo	

Repair kit



Fully assembled product



203.001.034.2

Oem Ref	Vehicle/Model	Engine
625218AM 622504AM	Daf	

Repair kit



Fully assembled product



203.001.035.2

Oem Ref	Vehicle/Model	Engine
628304AM 628276AM 628277AM	Daf	

Repair kit




Fully assembled product



203.001.036.2

Oem Ref	Vehicle/Model	Engine
622158AM 622107AM 622109AM	Scania	3 SERIES

Repair kit



Ø 100

Fully assembled product



203.001.037.2

Oem Ref	Vehicle/Model	Engine
625282AM 622190AM 622199AM 624199AM	Scania	2 - 3 SERIES

Repair kit



Fully assembled product



203.001.038.2

Oem Ref	Vehicle/Model	Engine
628131AM 629683AM	Scania	P-G-R-T SERIES 4 SERIES

Repair kit



Fully assembled product



203.001.039.2

Oem Ref	Vehicle/Model	Engine
629327AM 630361AM MINERAL OIL PENTOSIN	Man	

Repair kit



Fully assembled product



203.001.040.2

Oem Ref	Vehicle/Model	Engine
627736AM 629300AM	VOLVO	

Repair kit



Clutch Center Repair Kit

Fully assembled product



203.001.041.2

Oem Ref	Vehicle/Model	Engine
1000178631SP1AM 1000178631AM	Scania	P-G-R-T SERIES

Repair kit



Fully assembled product




203.001.042.2

Oem Ref	Vehicle/Model	Engine
970 150 0010	Mercedes	Actros Travego

Repair kit





Abs & Ebs Valve Repair Kits

www.iwinmarktruck.com.tr

Fully assembled product



205.001.001.2

Oem Ref	Vehicle/Model	Engine
400 500 925 2	Daf Scania Volvo	

Repair kit



Fully assembled product



205.001.002.2

Oem Ref	Vehicle/Model	Engine
For 400 500 081 0	Daf Scania Volvo	

Repair kit




Fully assembled product



205.001.003.2

Oem Ref	Vehicle/Model	Engine
FOR 472 195 040 0 472 195 041 0 472 195 042 0	Man Daf Scania Renault	

Repair kit




Fully assembled product



205.001.004.2

Oem Ref	Vehicle/Model	Engine
FOR 480 102 014 0 480 102 015 0	Man Daf Mack	

Repair kit




Fully assembled product



205.001.005.2

Oem Ref	Vehicle/Model	Engine
480 202 921 2	Mercedes Man Daf Iveco	

Repair kit



Fully assembled product



205.001.006.2

Oem Ref	Vehicle/Model	Engine
FOR 480 204 002 0	Mercedes Man Daf Iveco	

Repair kit



Fully assembled product



205.001.007.2

Oem Ref	Vehicle/Model	Engine
FOR 971 002 900 0 971 002 902 0 971 002 909 0	Man Scania Volvo Otogar Mack	

Repair kit



Fully assembled product







205.001.008.2

Oem Ref	Vehicle/Model	Engine
FOR 971 002 900 0 971 002 902 0 971 002 909 0	Man Scania Volvo Otogar Mack	

Repair kit





Ecas Solenoid Valve Repair Kit

www.iwinmarktruck.com.tr


Fully assembled product



204.001.001.2

Oem Ref	Vehicle/Model	Engine
FOR 472 880 001 0	Man Volvo Scania Daf Iveco Ford Mack	

Repair kit



Fully assembled product



204.001.002.2

Oem Ref	Vehicle/Model	Engine
FOR 472 880 001 0	Man Volvo Scania Daf Iveco Ford Mack	

Repair kit



Fully assembled product



204.001.003.2

Oem Ref	Vehicle/Model	Engine
472 880 934 2	Man Volvo Scania Daf Iveco Ford Mack	

Repair kit



Fully assembled product



204.001.004.2

Oem Ref	Vehicle/Model	Engine
FOR 472 880 001 0	Man Volvo Scania Daf Iveco Ford Mack	

Repair kit



Fully assembled product



204.001.005.2

Oem Ref	Vehicle/Model	Engine
FOR 472 880 061 0	Man Tg Series	

Repair kit



Fully assembled product



204.001.006.2

Oem Ref	Vehicle/Model	Engine
FOR 472 880 061 0	Man Tg Series	

Repair kit



Fully assembled product



204.001.007.2

Oem Ref	Vehicle/Model	Engine
FOR 472 880 061 0	Man Tg Series	

Repair kit



Fully assembled product



204.001.008.2

Oem Ref	Vehicle/Model	Engine
472 880 936 2	Man Tg Series	

Repair kit



Fully assembled product



204.001.009.2

Oem Ref	Vehicle/Model	Engine
472 880 937 2	Man Tg Series	

Repair kit




Fully assembled product



204.001.010.2

Oem Ref	Vehicle/Model	Engine
472 880 940 2	Scania Daf Iveco Evobus	

Repair kit



Fully assembled product



204.001.011.2

Oem Ref	Vehicle/Model	Engine
FOR 472 900 053 0	Mercedes Man Da Scania Renault	

Repair kit



Fully assembled product



204.001.012.2

Oem Ref	Vehicle/Model	Engine
FOR 472 900 053 0	Mercedes Man Da Scania Renault	

Repair kit



Fully assembled product



204.001.013.2

Oem Ref	Vehicle/Model	Engine
FOR 472 900 053 0	Mercedes Man Da Scania Renault	

Repair kit



Fully assembled product



204.001.014.2

Oem Ref	Vehicle/Model	Engine
472 900 009 2	Mercedes Man Daf Volvo Iveco	

Repair kit




Fully assembled product



204.001.015.2

Oem Ref	Vehicle/Model	Engine
472 905 004 2	Mercedes Man Daf Evobus	

Repair kit



Fully assembled product



204.001.016.2		
Oem Ref	Vehicle/Model	Engine
FOR K019819N50		

Repair kit





Relay Valve Repair Kit

Fully assembled product



206.001.001.2

Oem Ref	Vehicle/Model	Engine
1 487 010 007	Mercedes Man Daf Scania Iveco Renault IV Volvo	

Repair kit




Fully assembled product



206.001.002.2

Oem Ref	Vehicle/Model	Engine
1 487 010 366	Mercedes Volvo Trailers Buses	

Repair kit



Fully assembled product



206.001.003.2

Oem Ref	Vehicle/Model	Engine
973 011 000 2	Mercedes Man Daf Iveco Evobus Mack	

Repair kit



Fully assembled product



206.001.004.2

Oem Ref	Vehicle/Model	Engine
	Mercedes Man Daf Iveco Evobus Mack Renault Volvo Scania	973 011 SERIES

Repair kit



Fully assembled product



206.001.005.2

Oem Ref	Vehicle/Model	Engine
	Mercedes Man Daf Iveco Evobus Mack Renault Volvo Scania	973 011 SERIES

Repair kit




Fully assembled product



206.001.006.2

Oem Ref	Vehicle/Model	Engine
	Mercedes	973 011 SERIES
	Man	
	Daf	
	Iveco	
	Evobus	
	Mack	
	Renault	
	Volvo	
	Scania	

Repair kit



Fully assembled product




206.001.007.2

Oem Ref	Vehicle/Model	Engine
FOR AC577A	Renault Daf	

Repair kit





Gearbox Housing Valve Repair Kit

www.iwinmarktruck.com.tr

Fully assembled product



208.001.001.2

Oem Ref	Vehicle/Model	Engine
FOR	Mercedes	
421 350 083 0		
421 350 085 0		
421 350 087 0		

Repair kit




Fully assembled product



208.001.002.2

Oem Ref	Vehicle/Model	Engine
421 350 931 2	Mercedes	
000 260 70 68		

Repair kit




Fully assembled product



208.001.003.2

Oem Ref	Vehicle/Model	Engine
FOR	Mercedes	
421 350 083 0		
421 350 085 0		
421 350 087 0		

Repair kit



Fully assembled product



208.001.004.2

Oem Ref	Vehicle/Model	Engine
FOR	Mercedes	
421 351 135 0		
421 351 136 0		
421 351 137 0		
421 351 138 0		
421 351 140 0		
421 351 151 0		
421 351 152 0		

Repair kit




Fully assembled product



208.001.005.2

Oem Ref	Vehicle/Model	Engine
421 351 008 2	Mercedes	

Repair kit



Fully assembled product



208.001.006.2

Oem Ref	Vehicle/Model	Engine
For 421 350 070 0 421 350 072 0 001 260 19 63 001 260 47 63 001 260 85 63 002 260 19 63 002 260 20 63 002 260 40 63	Mercedes	

Repair kit



Fully assembled product



208.001.007.2

Oem Ref	Vehicle/Model	Engine
For 421 350 070 0 421 350 072 0 001 260 19 63 001 260 47 63 001 260 85 63 002 260 19 63 002 260 20 63 002 260 40 63	Mercedes	

Repair kit



Fully assembled product



208.001.008.2

Oem Ref	Vehicle/Model	Engine
FOR 421 351 070 0 001 260 20 63 001 260 48 63 A0012604863	Mercedes	

Repair kit



Fully assembled product



208.001.009.2

Oem Ref	Vehicle/Model	Engine
4724009222	Mercedes	

Repair kit



Fully assembled product



208.001.010.2

Oem Ref	Vehicle/Model	Engine
FOR 002 260 29 57 002 260 30 57 002 260 62 57 002 260 24 57 002 260 41 57 002 260 61 57	Mercedes	

Repair kit



Fully assembled product



208.001.011.2

Oem Ref	Vehicle/Model	Engine
FOR 002 260 29 57 002 260 30 57 002 260 62 57 002 260 24 57 002 260 41 57 002 260 61 57	Mercedes	

Repair kit



Fully assembled product



208.001.012.2

Oem Ref	Vehicle/Model	Engine
FOR 6038 202 036 6038 202 039 6038 202 042	Daf Renault Zf	

Repair kit



Fully assembled product



208.001.013.2

Oem Ref	Vehicle/Model	Engine
FOR SV3368 SV3367 81521706064 0012606257	Mercedes Man Daf Renault Volvo Zf	

Repair kit



Fully assembled product



208.001.014.2

Oem Ref	Vehicle/Model	Engine
FOR SV3368 SV3367 81521706064 0012606257	Mercedes Man Daf Renault Volvo Zf	

Repair kit





Trailer Control Valves Repair Kit

www.iwinmarktruck.com.tr

Fully assembled product



207.001.001.2

Oem Ref	Vehicle/Model	Engine
1 487 010 257	Dorse	

Repair kit



Fully assembled product



207.001.002.2

Oem Ref	Vehicle/Model	Engine
FOR 201 002 001	Dorse	

Repair kit




Fully assembled product



207.001.003.2

Oem Ref	Vehicle/Model	Engine
FOR 319 002 004 2 973 002 402 0 973 002 500 0	Dorse	

Repair kit



Fully assembled product



207.001.004.2

Oem Ref	Vehicle/Model	Engine
971 002 003 2	Dorse	

Repair kit



Fully assembled product



207.001.005.2

Oem Ref	Vehicle/Model	Engine
463 032 001 2	Dorse	

Repair kit





VINMARK

Handbrake Valve Repair Kit

www.iwinmarktruck.com.tr

Fully assembled product



209.001.001.2

Oem Ref	Vehicle/Model	Engine
961 723 001 2	Daf	
0513799	Man	
81.52315.6143	Renault	
1350477	Scania	
276081	Volvo	
For 961 723 401 0		

Repair kit



Fully assembled product



209.001.002.2

Oem Ref	Vehicle/Model	Engine
961 723 000 2	Daf	
0513798	Iveco	
FBU4563	Man	
003 430 5281	Mercedes-Benz	
A003 430	Renault	
3090943	Volvo	
93161152		

Repair kit



Fully assembled product



209.001.003.2

Oem Ref	Vehicle/Model	Engine
961 723 004 2	Daf	
1279601	Iveco	
20861969	Man	
93161490	Volvo	
21219960		
FOR 961 723 007 0		

Repair kit



Fully assembled product



209.001.004.2

Oem Ref	Vehicle/Model	Engine
81DB2K822AA	Ford	
APGA/6635		
FOR GA/29144		

Repair kit



Fully assembled product



209.001.005.2

Oem Ref	Vehicle/Model	Engine
FOR 9617231250	Mercedes	
FOR 1519266	Scania	
FOR 0034307381	Daf	
FOR 1935571		
DPM22A		
DPM23A		

Repair kit



Handbrake Valve Repair Kit

Fully assembled product



209.001.006.2

Oem Ref	Vehicle/Model	Engine
FOR 9617231110	Man	
FOR 1518236	Daf	
FOR 99100360497	Renault	
FOR 85500014558		
FOR 50105251112		
DPM60A		

Repair kit



Fully assembled product



209.001.007.2

Oem Ref	Vehicle/Model	Engine
FOR 9617230230	Daf	
FOR 1524295	Iveco	
FOR 500303739		
FOR 98474180		
DPM94AAX		
DPM95AAX		

Repair kit




Fully assembled product



209.001.008.2

Oem Ref	Vehicle/Model	Engine
FOR 9617222620	Daf	
1 487 010 297	Man	
FOR 1505327R	Renault	
FOR 81523156122	Scania	
1519251		
0 481 016 603		

Repair kit



Fully assembled product



209.001.009.2

Oem Ref	Vehicle/Model	Engine
FOR 9617210330	Daf	
FOR 1524301	Man	
FOR 81523156078	Volvo	
FOR 6876972		
HB1142		

Repair kit



Fully assembled product



209.001.010.2

Oem Ref	Vehicle/Model	Engine
FOR 9617210330	Daf	
FOR 1524301	Man	
FOR 81523156082	Volvo	
FOR 6876972		
HB1267		

Repair kit




Fully assembled product



209.001.011.2

Oem Ref	Vehicle/Model	Engine
FOR K038802 FOR A003 430 6881 DPM21A	Mercedes	

Repair kit



Fully assembled product



209.001.012.2

Oem Ref	Vehicle/Model	Engine
FOR 961 722 155 0 FOR 42086775 FOR 4747196 FOR 1102659544020	Man Iveco	

Repair kit



Fully assembled product



209.001.013.2

Oem Ref	Vehicle/Model	Engine
961 722 007 2 FOR 1105738 500005848 1105738 961 722 212 0	Scania Man Iveco	

Repair kit



Fully assembled product



209.001.014.2

Oem Ref	Vehicle/Model	Engine
FOR K038808 FOR A000 420 0284 DPM66A	Mercedes	

Repair kit



Fully assembled product



209.001.015.2

Oem Ref	Vehicle/Model	Engine
FOR K038805 FOR A003 430 7581 DPM24AK	Mercedes	

Repair kit



Fully assembled product



209.001.016.2

Oem Ref	Vehicle/Model	Engine
FOR 9617223250 FOR A0034305681 0 481 016 106 0 481 016 201 0 481 016 209	Mercedes	

Repair kit



Fully assembled product



209.001.017.2

Oem Ref	Vehicle/Model	Engine
9617010002 0695880 42480504 81523156048 0005868043 272700	Mercedes Man Scania Daf Iveco Volvo	

Repair kit



Fully assembled product



209.001.020.2

Oem Ref	Vehicle/Model	Engine
9617020002 0698509 502924708 A0025868843	Mercedes Daf Liebherr	

Repair kit



Fully assembled product



209.001.022.2

Oem Ref	Vehicle/Model	Engine
9617220032 0691984 42485350 272794 A0034303281	Mercedes Man Daf Iveco Volvo Renault	

Repair kit



Fully assembled product



209.001.024.2

Oem Ref	Vehicle/Model	Engine
9617220042 1519247 81523156106 A0034303381 9617220042	Mercedes Man Daf Iveco Renault	

Repair kit





Diesel Overflow valve

210.001.001.0

Oem Ref	Vehicle/Model	Engine	Details
457 070 0246	Mercedes	Axor Actros Arocs	M16x1.5 AA – 22/25



210.001.002.0

Oem Ref	Vehicle/Model	Engine	Details
906 092 12 10	Mercedes	Axor Actros Arocs Atego Econic	M16x1.5 4.5 Bar



210.001.003.0

Oem Ref	Vehicle/Model	Engine	Details
906 092 05 10	Mercedes	Axor Actros Arocs Atego Econic	M16x1.5 4.5 Bar



210.001.004.0

Oem Ref	Vehicle/Model	Engine	Details
541 070 02 46 541 070 05 46 541 070 06 46	Mercedes	Actros Neoplan	M16x1.5 AA – 22/25



210.001.005.0

Oem Ref	Vehicle/Model	Engine	Details
000 074 0515 11.20013.0003 0245187	Mercedes Man Daf		M14x1.5 1.5 Bar



210.001.006.0



Oem Ref	Vehicle/Model	Engine	Details
000 074 76 84	Mercedes		M14x1.5
1228128	Daf		1.5 Bar
0347 6293	Iveco		
51.11107.0024	Man		
11700231	Volvo		
50 00 570 007	Renault		

210.001.007.0



Oem Ref	Vehicle/Model	Engine	Details
239133	Mercedes		M14x1.5
1353622	Man		1 Bar
000 477 02 29	Renault		
81.54114-6054	Scania		
1 417 413 029	Volvo		
00 03 017 022			

210.001.008.0



Oem Ref	Vehicle/Model	Engine	Details
1917514	Scania		M16x1.5
1864034			5 Bar
1379215			

210.001.009.0



Oem Ref	Vehicle/Model	Engine	Details
51.11107.0020	Mercedes		M14x1.5
000 074 9984	Man		1.8 Bar
1358496	Scania		
3094570	Volvo		

210.001.010.0



Oem Ref	Vehicle/Model	Engine	Details
1427453	Scania		

Diesel Overflow valve

210.001.011.0

Oem Ref	Vehicle/Model	Engine	Details
1677850	Volvo		M8x1



210.001.012.0

Oem Ref	Vehicle/Model	Engine	Details
74 20 430 101 20430101	Renault Volvo		M10x1.5



210.001.013.0

Oem Ref	Vehicle/Model	Engine	Details
74 03 095 479 3095479	Renault Volvo		M16x1.5 4.5 Bar



210.001.014.0

Oem Ref	Vehicle/Model	Engine	Details
20765317 3097433	Volvo		M14x1.5



210.001.015.0

Oem Ref	Vehicle/Model	Engine	Details
3092544 3964739	Volvo		M16x1.5



210.001.016.0



Oem Ref	Vehicle/Model	Engine	Details
20450468	Volvo		M16x1.5 4.8 Bar

210.001.017.0



Oem Ref	Vehicle/Model	Engine	Details
74 21 022 032 74 21 458 307 20715052 21022032 21458307	Renault Volvo		M16x1.5 3.2 Bar

210.001.018.0



Oem Ref	Vehicle/Model	Engine	Details
74 20 754 813 20754813 20776177	Renault Volvo		M16x1.5

210.001.019.0



Oem Ref	Vehicle/Model	Engine	Details
74 20 715 049 20715049	Renault Volvo		

210.001.020.0



Oem Ref	Vehicle/Model	Engine	Details
11996309	Volvo		M14x1.5 M16x1.5

Diesel Overflow valve

210.001.021.0

Oem Ref	Vehicle/Model	Engine	Details
51.11107.0016 51.11107.0026	Man		M14x1.5 AA19



210.001.022.0

Oem Ref	Vehicle/Model	Engine	Details
81.12505.0004	Man		M14x1.5 AA19



210.001.023.0

Oem Ref	Vehicle/Model	Engine	Details
541 070 0246 541 070 0546 541 070 0646	Mercedes		M16x1.5 AA 22/24



210.001.024.0

Oem Ref	Vehicle/Model	Engine	Details
541 098 0057	Mercedes		M18x1.5 AA19



210.001.025.0

Oem Ref	Vehicle/Model	Engine	Details
457 070 0246	Mercedes		M16x1.5 AA 22/24



210.001.026.0			
Oem Ref	Vehicle/Model	Engine	Details
000 091 2210	Mercedes	Actros Antos Arocs Axor Setra	



210.001.027.0			
Oem Ref	Vehicle/Model	Engine	Details
5 0032 8251	Iveco		



Diesel Overflow valve